



Approved

The well system appears operational and in acceptable condition. The property qualifies for consideration under current coverage guidelines.

System evaluation score: 100/100

MEMBER & PROPERTY

OWNER NAME
Victor Salinas

EMAIL
vsalinas@email.net

PHONE
555-512-7733

PROPERTY ADDRESS
302 Laurel Ridge Road, Gettysburg, PA, 17325

INSPECTION SOURCE

INSPECTOR
Diana Reyes

COMPANY
Summit Well & Pump

INSPECTION DATE
April 20, 2026

REPORT ID
WRP-2026-GLD3J

WELL SYSTEM DETAILS

WELL TYPE
drilled

WELL DEPTH
195 ft

PUMP TYPE
submersible

PUMP AGE
5 years

PRESSURE TANK AGE
5 years

CONDITION ASSESSMENT

PHYSICAL CONDITION RATINGS

Casing: Good

Well Cap: Good

Wiring: Good

OPERATIONAL CHECKS

- System Operational
- Pressure Within Range
- Flow Rate Acceptable
- Site Clearance Met
- No Visible Leaks
- No Safety Issues
- No Contamination Risk

EVALUATION NOTES

- All evaluated criteria are within acceptable parameters.

FINDINGS & RECOMMENDATIONS

INSPECTOR NOTES

Inspection complete. Water sample submitted to lab — results pending.

IMPORTANT DISCLAIMER

This report is based solely on the visible and accessible conditions observed during the inspection conducted on the date noted above. It does not constitute a guarantee of the well system's future performance, longevity, or suitability for any particular use. The inspection is limited to items and areas accessible at the time and does not include assessment of concealed, underground, or inaccessible components.

Final coverage eligibility, participation decisions, and warranty terms remain subject to Welgard's standard review process and program guidelines. This report is intended for internal operational use and authorized member communication only. It should not be relied upon as a comprehensive engineering assessment or substitute for professional engineering consultation.